

Department of Energy

Richland Operations Office P.O. Box 550 Richland, Washington 99352

059112

JUN 0 1 1998

Mr. Mike A. Wilson, Manager Nuclear Waste Program State of Washington Department of Ecology P. O. Box 47600 Olympia, Washington 98504-7600

Dear Mr. Wilson:

SUBMITTAL OF THE PUREX SUVEILLANCE AND MAINTENANCE PLAN TO COMPLETE HANFORD FEDERAL FACILITY AND CONSENT ORDER MILESTONE M-80-00 COMPLETE PUREX AND UO, PLANT FACILITY TRANSITION PHASE AND INITIATE THE SURVEILLANCE AND MAINTENANCE PHASE

Attached is the Surveillance and Maintenance Plan for the PUREX Facility, DOE/RL-98-35, Rev. 0. Your approval of this plan will satisfy the final criterion for completing Hanford Federal Facility Agreement and Consent Order (Tri-Party Agreement) Milestone M-80-00, "Complete PUREX and UO₃ Plant Facility Transition Phase and Initiate the Surveillance and Maintenance Phase," due July 31, 1998.

If you have any questions, please feel free to contact Mr. T. W. Ferns at 372-0649.

MN 1998

SE PECEIVED

TO MC

TO ME CEIVED

TO MC

T

Sincerely,

T. W. Ferns, Project Manager Remedial Actions Project

George H. Sanders, Administrator Hanford Tri-Party Agreement

Attachment

cc w/attach:

R. J. Julian, Ecology

cc w/o attach:

R. P. Henckel, BHI

D. R. Sherwood, EPA

Attachment 2

059004

DOE/RL-98-35

SURVEILLANCE AND MAINTENANCE PLAN FOR THE PLUTONIUM URANIUM EXTRACTION (PUREX) FACILITY

APPROVAL:

T. W. Ferns, Project Manager Restoration Projects Division U.S. Department of Energy Richland Operations Office

L. E. Rogers, PUREX Program Manager

Transition Program Division U.S. Department of Energy Richland Operations Office

R. J. Julian, PUREX Project Manager State of Washington Department of Ecology